Built-in Systems Interface

C4D4 Boot or rear door sills lighting fault.

F98A Engine relay unit : fault front right side light.

F98B Engine fuse box : Front left side light fault.

F98F Engine fuse box : Front left fog lamp fault.

F990 Engine relay unit : front right fog lamp fault.

Injection/ignition

P0563 Battery voltage fault

Properties

status Intermittent
Caracterisation of the fault Voltage too high

List of associated variables

Engine speed 2168 rpm
Vehicle speed 32 kph
Richness regulation status Closed loop

P0501 Fault: vehicle speed sensor signal

Properties

Cause Distant status Intermittent Caracterisation of the fault Coherence

List of associated variables

Engine speed 1799 rpm
Vehicle speed 38 kph
Richness regulation status Closed loop

ABS/traction control

P0563 ECU supply overvoltage fault.

Properties

From. Local.

status Temporary

Caracterisation of the fault Not characterised

List of associated variables

Vehicle speed11 KphFront left wheel speed11 KphFront right wheel speed11 KphLeft rear wheel speed11 KphRight rear wheel speed11 Kph

EBA regulation Deactivated
EBD regulation Deactivated
Anti-slip regulation with action on brakes(BASR) Deactivated

Anti-Slip with action on engine torque disconnected(ASR/ESR)

Anti-engine brake regulation(MSR)

Deactivated

Anti-Slip regulation with action on engine torque(ASR)

Deactivated

Elactronic Stability Program(ESP)regulation

Deactivated

ABS regulation

Deactivated

Reciculation pump activated No

Electric parking brake status

Unspecified status

Status of the "assisted holding" function Fault

Braking status No braing in progress

Yaw angle speed 26 ° /s

Transverse acceleration 2.6 m/s2

Steering wheel angle 56.7 °

Distance travelled since last time ignition switched on 0.2 km

Control unit supply voltage 17.0 V

Braking pressure 0 Bars

Longitudinal acceleration from the wheel speed sensor -0.08 m/s2

Properties

From. Distant.

status Permanent fault
Caracterisation of the fault Not characterised

U1313 Incorrect rear left-hand wheel speed transmitted by the EBS/ESP ECU

Properties

From. Distant.

status Permanent fault
Caracterisation of the fault Not characterised

U1313 Vehicle speed transmitted by the ABS

Properties

From. Distant.

status Permanent fault

Caracterisation of the fault No signal

List of associated variables

Fault appearance number 3

Engine speed 2080 rpm Turbine speed 1568 rpm Automatic gearbox output speed 704 rpm 5.35 bar(s) Oil pressure 5.4 bar(s) Guide pressure Gear engaged Canging gear Lock-up Converter Line pressure modulating electrovalve output Deactivated Position of the gear lever Position D OIL TEMPERATURE 30 °C Accelerator pedal position 21.45 %

Engine torque theoretical CAN 078 Nm
Control unit supply voltage 18.0 Volt(s)

Power steering electric punp unit

C1208 Fault : vehichle speed ingormation

Properties

From.

Caracterisation of the fault

List of associated variables

Communication error

C1210 Fault engine running

Properties

From. status

Caracterisation of the fault

List of associated variables

Communication error

Headlamp height adjuster /directional headlamp

C1142 Front vehicle height sensor signal

B1117 Supply voltage too high

Engine relay unit

F98A Fault: front right side light
F98B Fault: front left side light
F98F Fault IHF front foglamp
F990 Fault rHF foglamp

Local.

Intermittent.

Short-circuit to positive or circuit open

Distant.

Permanent fault
Not characterised